



THERMOGRAPHIC REPORT

Report Date: 09/25/03

Any Company	LOCATION: MAIN TRANSFORMER
123 Any Street	EQUIPMENT ID: MAIN TRANSFORMER
Any City, Michigan	SEVERITY: SERIOUS

TH710001.SIT • 9/15/2003 • 10:06:21 AM



	Ref.	Rect2
Emiss.	1.0	1.0
Avg		88.6 °C
Min		46.6 °C
Max	63.5 °C	130.0 °C
Delta		66.5 °C


PROBLEM	X3 OVERHEATING
RECOMMENDATION	REPLACE
INSPECTOR	CHRIS KIDD
ASSISTANT	BRIAN BURGESS
CORRECTIVE ACTION TAKEN	

THERMOGRAPHIC REPORT

Report Date: 09/25/03

Any Company	LOCATION: MAIN DP #2
123 Any Street	EQUIPMENT ID: SHUTTLE 11 & 12
Any City, Michigan	SEVERITY: INTERMEDIATE

TH710003.SIT • 9/15/2003 • 11:41:24 AM



	Ref.	Rect2
Emiss.	1.0	1.0
Avg		35.6 °C
Min		25.7 °C
Max	29.4 °C	43.8 °C
Delta		14.4 °C


PROBLEM	FAILING DISCONNECT
RECOMMENDATION	REPLACE
INSPECTOR	CHRIS KIDD
ASSISTANT	BRIAN BURGESS
CORRECTIVE ACTION TAKEN	

THERMOGRAPHIC REPORT

Report Date: 09/25/03

Any Company	LOCATION: MAIN DP #2
123 Any Street	EQUIPMENT ID: SHUTTLE 14 & 15
Any City, Michigan	SEVERITY: MINOR

TH710004.SIT • 9/15/2003 • 11:41:38 AM



	Ref.	Rect2
Emiss.	1.0	1.0
Avg		33.8 °C
Min		27.0 °C
Max	29.2 °C	38.7 °C
Delta		9.5 °C


PROBLEM	FAILING DISCONNECT
RECOMMENDATION	REPLACE
INSPECTOR	CHRIS KIDD
ASSISTANT	BRIAN BURGESS
CORRECTIVE ACTION TAKEN	

THERMOGRAPHIC REPORT

Report Date: 09/25/03

Any Company	LOCATION: MAIN DP #2
123 Any Street	EQUIPMENT ID: SHUTTLE 17 & 18
Any City, Michigan	SEVERITY: INTERMEDIATE

TH710005.SIT • 9/15/2003 • 11:42:03 AM



	Ref.	Rect2
Emiss.	1.0	1.0
Avg		51.3 °C
Min		26.3 °C
Max	39.0 °C	69.3 °C
Delta		30.3 °C

PROBLEM	FAILING DISCONNECT
RECOMMENDATION	REPLACE
INSPECTOR	CHRIS KIDD
ASSISTANT	BRIAN BURGESS
CORRECTIVE ACTION TAKEN	